Top Attachments

For dial & test indicators

FA1300	M6	Plastic F.A. 8 mm		Dovetail 1/4*
FA1301	M6	Plastic F.A. 3/8"		Dovetail 1/4*
FA1400	M6	2SM Metal F.A. 6 mm, 8 mm, 3/8"	The state of the s	Universal Swivel Clamp Manual Transport of the Control of the Con
FA1500	M6	Metal F.A. 6 mm, 8 mm, 3/8"		Universal Swivel Clamp



Top Attachments

Quick Release AD4000

Enables a quick change to the equipment without having to fiddle with screws and threads.

Simply pull back the red sleeve and slot in the Noga arm into the Quick Release attachment

Quick Release can be held by a range of Noga arms.

Features bottom external thread M6 and top external thread 1/4" UNC.



Clamps for top attachment

NF0125	M6 EXT.	Clamp 1"	0-25mm (0'-1") M6
DG0125	M6 EXT.	Clamp 2"	0-50.8mm (0"-2") M6

45 mm Clamp CS4550


The strong CS4550 clamp with its special soft grip expands onto round and flat surfaces up to 45 mm.

Features internal threads: 2 x 1/4", 2 x 3/8" 1 x 6 mm, 1 x 8 mm.





Accessories







Accessories

3 Point Clamp

	Dia. Post	Dia. Arm	
PH1307	8	8	For Holder PH5000
PH0315	10	8	For Holder PH3100
PH0310	14	12	For Holders: PH2040 PH6400 PH6410
PH0312	16	16	For Holders: PH4016, PH6600, PH6610
PH0313	18	16	For Holders: PH6800, PH6810

Knobs

DG0160	Knob for NF & DG Holders	
MG1620	Knob for MG Holders	
MA0100	Knob for MA Holders	

Screws

DG0340	M5 x 9	Replacement screw for FA1500.	
DG0141	M4 x 12	Replacement screw for DG10503, DG10533, MG10503, MG10533, NF 10403, NF 10433, DG6160 & MG6161.	

